Coiled Tubing Bias Welds Recent Failures Trend



Tomas Padron, Coiled Tubing Research and Engineering (CTRE)

October 29th, 2014 ICoTA Roundtable, Calgary, Canada



Bias Weld Failures - Outline

- Background Information
- Bias Weld Failures Causes
- Main Ideas



Bias Weld Failures - Background

Bias weld: plasma arc weld at 45° to joint steel strips ...After conforming the pipe it forms a helical weld





Bias Weld Failures - Background

Bias weld failures trend in BHI:



Bias Weld Failures - Background



- CT90 and CT100+: 88% of bias weld failures
- 68% of the failures associated with 2" pipe
- Strings from the 3 CT manufacturers

Bias Weld Failures - Causes



Corrosion Operations, Fatigue, and H2S Cracking represent 84% of the bias weld failures

6 | 2014 ICoTA Roundtable – Bias Weld Failures

Corrosion Operations: failures associated with corrosion damage caused by fluids used during operations.



- Six (6) CT failures occurred while milling plugs in Alice – USA.
- String characteristics:
 - 2" OD x tapered
 - 90 Grade
 - Basically new strings
- All the failures occurred on bias welds.









- On 3 failures: internal pitting corrosion on the bias weld region.
- Fatigue cracks starting at these pits
- High pressure regime (around 7,000 psi).
- Fluid: recycled fluid "treated" with biocide.









- Sulfur (S) was found within the internal pits
- Recycled fluid analyses revealed:
 - Sulfur, pungent odors of rotten eggs, and sulfide in the form of black precipitates
 - 4.2 5.2 million bacteria per ml
 - APBs and SRBs





Failure: Pinhole; Date: November 2013; String: 2-3/8" x 0.156" – CT100+ Fluid: Customer supplied "treated" sea water (oxygen scavenger + biocide)



Failure: Ext. corrosion on bias weld; Date: October 2013; String: 2" x Tapered – CT90 Fluids: fracturing fluid + acid mix with inhibitor

- Corrosion Operations:
 - The examples showed a greater susceptibility to corrosion damage on the bias weld region – this is considered as "expected" but....Could this be a topic for investigation and improvement?



H2S cracking: failure by internal cracking due to the exposure to a sour environment. H2S sources could be different, i.e. well, contaminated fluid, etc.



- Three (3) CT failures occurred while milling plugs in Alice USA.
- String characteristics: 2" OD x tapered 90 Grade / Basically new strings
- Failures occurred as fractures at bias welds





- Internal corrosion damage very mild or absent no fatigue cracking associated with isolated pits
- Internal cracking on the bias welds "cleavage" features similar to cracking due to exposure to H2S





- Fluid: recycled fluid "treated" with biocide
- Sulfur was observed on some shallow pits
- Fluid analyses revealed the presence of SRBs
- "Localized sour environments" – Bias weld weakest point



um Electron Image 1

Bias Weld Failures – Contaminated Recycled Fluid

- Corrective actions:
 - Treating for bacteria in the system (including tanks)
 - Treating circulating fluid
 - Treating stagnant fluid





Not common to have "pure" fatigue failures

- Strings: 2" x tapered CT100+
- Operating Pressure: 6,000 7,000 psi
- Strains at bias weld locations: 1.8% 2.3%
- SFL used at bias weld locations: around 50%



Bias Weld Failures – Fatigue - Main Ideas

- Analysis of strings records showed:
 - Most of the retired strings without failures SFL at bias welds < 50%
 - Failures at bias welds SFL \ge 50%





22 2014 ICoTA Roundtable – Bias Weld Failures



At low strain (1.4%) the measured bias weld fatigue life was 87% of the pipe base material

23 | 2014 ICoTA Roundtable – Bias Weld Failures



At 1.8% strain most of the values were lower than 80% (55% - 77%)

24 | 2014 ICoTA Roundtable – Bias Weld Failures



At 2.1% strain the reduction of fatigue life at the bias weld is more significant (below 70%)



Similar to 2.1% strain (bias weld fatigue life around 60s% of the pipe)



From the failures and the fatigue data it can be inferred that a bias weld derating is required for strings CT100 and up

De-rating should consider strain (reel and gooseneck):



Original – no de-rating

De-rating

Further fatigue testing on used bias welds (from strings retired from service) confirmed that the de-rating was required.

Bias Weld Failures – Main Ideas

- Between 2011 and 2013 and abnormal increase of failures associated with bias welds was observed.
- Strings involved: CT90 and 100+; mainly 2" OD; from the 3 CT manufacturers
- Causes of failures:
 - Corrosion operations
 - H2S cracking
 - Fatigue

Bias Weld Failures – Main Ideas

- Corrosion operations and H2S cracking:
 - Bias weld more susceptible to corrosion damage Improvement?
 - Mainly associated with recycled fluid contaminated with bacteria
 - Corrective actions: treatment of system, fluid, and stagnant conditions

- Fatigue failures:
 - Associated with high strained CT100+ bias welds (1.8% to 2.3%)
 - Fatigue data confirmed need of de-rating factor for CT100+ bias welds
 - De-rating depending on level of strain

Coiled Tubing Bias Welds Recent Failures Trend THANK YOU QUESTIONS?



October 29th, 2014 ICoTA Roundtable, Calgary, Canada



Acknowledgments

- CTRE
- Steven Craig and BHI USA land staff

Backup



Great Yarmouth P2216



- Internal corrosion damage very mild or absent no fatigue cracking associated with isolated pits
- Internal cracking on the bias welds "cleavage" features similar to cracking due to exposure to H2S





37 | 2014 ICoTA Roundtable – Bias Weld Failures

- Date: January 2013
- String: 1-3/4" x tapered CT80
- Failure: two cracks on bias welds
- Well: 37 psi H2S partial pressure
- Use of only H2S scavenger not anti-cracking inhibitor
- Cracking on bias welds due to Sulfide Stress Corrosion Cracking (SSCC).



BW/Pipe ratios vs Hoop Stress





 Bias weld Charpy energy at room temp. lower than base metal (16% to 35%)..mode of fracture: cleavage

Notch Location	Impact Values (ft-lbf)	Average Impact Values (ft-lbf)	
Bias Weld	6.6	4.5 (brittle – cleavage)	
	4.8		
	7.2		
	4.2		
	1.6		
	2.8		
Parent Metal	27.0	27.3 (ductile - dimples)	
	28.0		
	27.4		
	26.8		
Bias Weld	4.6	8.9 (brittle – cleavage)	
	10.0		
	10.2		
Parent Metal	26.0	27.7 (ductile – dimples)	
	29.2		
	28.0		

40 | 2014 ICoTA Roundtable – Bias Weld Failures